

**TMS320VC5470**  
**Digital Signal Processor**  
**Silicon Errata**

SPRZ009E  
December 2001 – Revised May 2003



Copyright © 2003, Texas Instruments Incorporated

### REVISION HISTORY

This revision history highlights the technical changes made to SPRZ009D to make it an SPRZ009E revision.

**Scope:** This document has been reviewed for technical accuracy; the technical content is up-to-date as of the specified release date including the following changes.

PAGE(s) NO.	ADDITIONS/CHANGES/DELETIONS
7	Revised "UART (Modem or IrDA) Interrupt Reset" advisory.

## Contents

<b>1</b>	<b>Introduction</b> .....	<b>4</b>
1.1	Quality and Reliability Conditions .....	4
	TMX Definition .....	4
	TMP Definition .....	4
	TMS Definition .....	4
1.2	Device and Development-Support Tool Nomenclature .....	4
<b>2</b>	<b>Known Design Marginality/Exceptions to Functional Specifications</b> .....	<b>6</b>
	Far Branches/Calls/Interrupts from Active Repeat Blocks (BRAf) .....	6
	UART (Modem or IrDA) Interrupt Reset .....	7
	Round (RND) Instruction Clears Pending Interrupts .....	8
	WRITA/MVDP .....	8
	SDRAM 16-Bit-Wide Little-Endian Mode .....	9
	Potential Bus Contention Between FLASH Reads and SDRAM Writes .....	9
	Read/Reset of the SPI_STATUS Register is Not Working Properly .....	10
	SDRAM and FLASH Cannot Both be 16-Bit-Wide Busses .....	10
	Minimum SPI PTV of 1 Can Cause Errors on Rising Edge-Triggered Reads .....	11
	SPI RE and WE Status Complete is Indicated Before the Last Bit is Processed .....	11
	Reset During 16M/64M SDRAM Accesses Can Prevent the Device From Rebooting .....	12
	ARM/WAIT Does Not Operate Correctly .....	13
<b>3</b>	<b>Documentation Support</b> .....	<b>14</b>

## 1 Introduction

This document describes the silicon updates to the functional specifications for the TMS320VC5470 silicon. The advisories are applicable to the TMS320VC5470 (257-ball MicroStar BGA™, GHK suffix).

### 1.1 Quality and Reliability Conditions

#### TMX Definition

Texas Instruments (TI) does not warranty either (1) electrical performance to specification, or (2) product reliability for products classified as “TMX.” By definition, the product has not completed data sheet verification or reliability performance qualification according to TI Quality Systems Specifications.

The mere fact that a “TMX” device was tested over a particular temperature and voltage ranges should not, in any way, be construed as a warranty of performance.

#### TMP Definition

TI does not warranty product reliability for products classified as “TMP.” By definition, the product has not completed reliability performance qualification according to TI Quality Systems Specifications; however, products are tested to a published electrical and mechanical specification.

#### TMS Definition

Fully-qualified production device.

### 1.2 Device and Development-Support Tool Nomenclature

To designate the stages in the product development cycle, TI assigns prefixes to the part numbers of all TMS320™ DSP devices and support tools. Each TMS320™ DSP commercial family member has one of three prefixes: TMX, TMP, or TMS. Texas Instruments recommends two of three possible prefix designators for support tools: TMDX and TMDS. These prefixes represent evolutionary stages of product development from engineering prototypes (TMX/TMDX) through fully qualified production devices/tools (TMS/TMDS).

Device development evolutionary flow:

- TMX** Experimental device that is not necessarily representative of the final device’s electrical specifications
- TMP** Final silicon die that conforms to the device’s electrical specifications but has not completed quality and reliability verification
- TMS** Fully qualified production device

Support tool development evolutionary flow:


- TMDX** Development-support product that has not yet completed Texas Instruments internal qualification testing.
- TMDS** Fully qualified development-support product

TMX and TMP devices and TMDX development-support tools are shipped with appropriate disclaimers describing their limitations and intended uses. Experimental devices (TMX) may not be representative of a final product and Texas Instruments reserves the right to change or discontinue these products without notice.

TMS devices and TMDS development-support tools have been characterized fully, and the quality and reliability of the device have been demonstrated fully. TI's standard warranty applies.

Predictions show that prototype devices (TMX or TMP) have a greater failure rate than the standard production devices. Texas Instruments recommends that these devices not be used in any production system because their expected end-use failure rate still is undefined. Only qualified production devices are to be used.

The device revision can be determined by the lot trace code marked on the top of the package. The location for the lot trace codes for the GHK package is shown in Figure 1. The location of other markings may vary per device.



NOTE: Qualified devices in the GHK package are marked with the letters "DV" at the beginning of the device name, and nonqualified devices in the GHK package are marked with the letters "XDV" or "PDV" at the beginning of the device name.

**Figure 1. Example, Typical Lot Trace Code for TMS320VC5470 (GHK)**

## 2 Known Design Marginality/Exceptions to Functional Specifications

Table 1. Summary of Advisories

Description	Revision Affected	Page
Far Branches/Calls/Interrupts from Active Repeat Blocks (BRAf)	Initial Silicon	6
UART (Modem or IrDA) Interrupt Reset	Initial Silicon	7
Round (RND) Instruction Clears Pending Interrupts	Initial Silicon	8
WRITa/MVDP	Initial Silicon	8
SDRAM 16-Bit-Wide Little-Endian Mode	Initial Silicon	9
Potential Bus Contention Between FLASH Reads and SDRAM Writes	Initial Silicon	9
Read/Reset of the SPI_STATUS Register is Not Working Properly	Initial Silicon	10
SDRAM and FLASH Cannot Both be 16-Bit-Wide Busses	Initial Silicon	10
Minimum SPI PTV of 1 Can Cause Errors on Rising Edge-Triggered Reads	Initial Silicon	11
SPI RE and WE Status Complete is Indicated Before the Last Bit is Processed	Initial Silicon	11
Reset During 16M/64M SDRAM Accesses Can Prevent the Device From Rebooting	Initial Silicon	12
ARM/WAIT Does Not Operate Correctly	Initial Silicon	13

### Advisory

#### *Far Branches/Calls/Interrupts from Active Repeat Blocks (BRAf)*

**Revision(s) Affected:** Initial Silicon

**Details:** When a block repeat is interrupted by a far call, far branch, or interrupt to another page; and a program memory address in the called routine happens to have the same lower 16 bits as the block-repeat end address (REA), a branch to the 16-bit block-repeat start address (RSA) is executed on the current page until the block-repeat counter decrements to 0. The XPC is ignored during these occurrences.

**Workaround:** Use one of the following workarounds:

1. If the called routine must be on a different page and has a program memory address that has the same lower 16 bits as the REA, save ST1 and clear the BRAf in the vector table before entering the called routine with the following two instructions:
 

```
PSHM ST1
RSBX BRAf
```

Then, restore ST1 before returning from the called routine. In the case of an interrupt service routine, these two instructions can be included in the delay slots following a delayed-branch instruction (BD) at the interrupt vector location. Then, the ST1 is restored before returning from the routine. With this method, BRAf is always inactive while in the called routine. If BRAf was not active at the time of the call, the RSBX BRAf has no effect.
2. Put the called routine on the same page as the interruptible block-repeat code. This can be achieved automatically by placing the interrupt vector table and the interrupt service routines or other called routines on the overlay pages. If this approach is used, far branches/calls are not necessary and the situation is completely avoided.
3. Avoid putting the called routine on other pages where a program memory address has the same lower 16 bits as the REA.
4. Use the BANZ instruction as a substitute for the block repeat.

**Advisory***UART (Modem or IrDA) Interrupt Reset*

**Revision(s) Affected:** Initial Silicon

**Details:** There are two interrupt conditions, which can cause undesirable UART (Modem or IrDA) behavior. These two interrupt conditions can be found in IT\_TYPE [bits 5:1] of UART\_ISR (FFFF:1028) or UART\_IRDA\_ISR (FFFF:0828) as defined below:

- 00110 => RX Time Out (priority level 2)
- 00010 => RHR Interrupt (priority level 2)

**Workaround:** When any UART (Modem or IrDA) interrupt is received, check the IT\_TYPE for either an RX Time Out or RHR Interrupt as defined above.

If the interrupt has been set due to either the RX Time Out or RHR Interrupt, then perform the following maneuvers to reset the interrupt condition:

1. Disable all the interrupts by writing '0' into UART\_IER (FFFF:1024) or UART\_IRDA\_IER (FFFF:0824).
2. Read from UART\_RHR (FFFF:1000) or UART\_IRDA\_RHR (FFFF:0800) until the FIFO is empty. The FIFO will be empty when UART\_LSR (FFFF:1014) or UART\_IRDA\_LSR (FFFF:0814) is read with '0' in RX\_FIFO\_E [bit 0].
3. If the RHR read does not clear the interrupt, use the RESET\_REG (FFFF:2F18), UART\_MODEM\_RESET [bit 8] or UART\_IRDA\_RESET [bit 7], to reset the UART (Modem or IrDA) peripheral. The peripheral reset should be active for at least 8 ARM CPU clock cycles. After reset, re-initialize all of the UART (Modem or IrDA) registers to the proper settings needed for the application.
4. Return to normal operation.
5. If the interrupt has been set due to any other interrupt condition, then the interrupt can be reset normally.
6. To reduce the possibility of RX Time Out and/or RHR interrupts, match the RX FIFO size setting to the expected number of words.

If the UART (Modem or IrDA) is unused:

- Set the CLKM\_REG (FFFF:2F00) block clock stop bit, UART\_MODEM\_CLK\_STOP [bit 9] or UART\_IRDA\_CLK\_STOP [bit 8]. This will disable the peripheral clock until the UART is actually needed. Also, set the WAKEUP\_REG (FFFF:2F08) bit, UART\_MODEM\_WAKEUP [bit 9] or UART\_IRDA\_WAKEUP [bit 8]. This will prevent the UART (Modem or IrDA) clock from starting, if any interrupt is detected. This value is copied to CLKM\_REG, if an interrupt occurs.

No corrections are planned for future devices.

**Advisory***Round (RND) Instruction Clears Pending Interrupts*

**Revision(s) Affected:** Initial Silicon

**Details:** The RND (round) instruction opcode is decoded incorrectly and will write to the interrupt flag register (IFR) with the data from the data write bus (E bus). Therefore, it could cause the pending interrupt to be missed.

**Workaround:** Do not use the RND instruction. Replace the RND instruction with an ADD instruction as follows:

<b>For this instruction ...</b>	<b>Use ...</b>
RND src[,dst]	ADD #1,15,src[,dst]

**Advisory***WRITA/MVDP*

**Revision(s) Affected:** Initial Silicon

**Details:** If a WRITA or MVDP instruction executing from a SARAM block performs a write to any SARAM block that is immediately followed by any read (including DMA or instruction fetch) of the same address that is written to, the read data may be corrupted.

**Workaround:** Use one of the following workarounds:

1. Avoid using WRITA/MVDP to write to an area in memory that will be executed as code immediately following the WRITA/MVDP.
2. Rearrange the code so that a read access does not immediately follow the WRITA/MVDP instruction with an address that is identical to the last address written to. Use a dummy write if necessary.
3. Avoid DMA reads in an area of program SARAM that is written to by WRITA/MVDP.



**Advisory***SDRAM 16-Bit-Wide Little-Endian Mode*

**Revision(s) Affected:** Initial Silicon

**Details:** The SDRAM Big-/Little-Endian modes are supported as follows:

- SDRAM 32-bit-wide Big-Endian mode is supported
- SDRAM 16-bit-wide Big-Endian mode is supported
- SDRAM 32-bit-wide Little-Endian mode is supported
- SDRAM 16-bit-wide Little-Endian mode is **not** supported

**Workaround:** If Little-Endian operation is required, use only the 32-bit-wide mode. No corrections are planned for future revisions.

**Advisory***Potential Bus Contention Between FLASH Reads and SDRAM Writes*

**Revision(s) Affected:** Initial Silicon

**Details:** On reads from FLASH, the output enable to data bus three-state could be slow enough to cause reliability contention with SDRAM write operations.

**Workaround:** Avoid this reliability contention by using the internal SRAM to run code and intermediate data from the FLASH. Also, all stacks should be located in internal SRAM.

No corrections are planned for future revisions.

**Advisory***Read/Reset of the SPI\_STATUS Register is Not Working Properly*

**Revision(s) Affected:** Initial Silicon

**Details:** When the external CLKX\_SPI prescaled SPI\_CLOCK clock is active (which could be every 4, 8, 16, 32, 64, 128, 256 SPI\_CLOCK events depending on the state of PTV in SPI\_SET (FFFF:2000)) on the same clock cycle as the read/reset, then the reset will not take place as expected. This creates an inconsistent SPI status register reset phenomena.

**Workaround:** There are three potential workarounds.

1. Perform a read loop until the reset is detected.
2. Use a slower CLKX\_SPI clock rate to improve the odds of a reset the first time. This should be incorporated with number 1 above.
3. Turn off the SPI\_CLOCK at CLKM\_REG (FFFF:2F00) during the read/reset ensuring that the CLKX\_SPI will not interfere with the register reset. The WAKEUP\_REG register (FFFF:2F08) should be changed to match the CLKM\_REG in case an interrupt occurs prior to the read/reset.

No corrections are planned for future revisions.

**Advisory***SDRAM and FLASH Cannot Both be 16-Bit-Wide Busses*

**Revision(s) Affected:** Initial Silicon

**Details:** For a 32-bit FLASH read following a 32-bit SDRAM write, the first 16-bit word of the 32-bit FLASH read can give incorrect data due to improper address generation. This condition can occur when both the SDRAM and FLASH are configured for 16-bit-wide data busses. Other combinations of 16-bit and 32-bit-wide busses do not exhibit this behavior as described in the following:

- 16-bit-wide FLASH and 16-bit-wide SDRAM busses can fail.
- 16-bit-wide FLASH and 32-bit-wide SDRAM busses, no failures.
- 32-bit-wide FLASH and 16-bit-wide SDRAM busses, no failures.
- 32-bit-wide FLASH and 32-bit-wide SDRAM busses, no failures.

**Workaround:** No workaround exists. No corrections are planned for future revisions.

**Advisory***Minimum SPI PTV of 1 Can Cause Errors on Rising Edge-Triggered Reads*

**Revision(s) Affected:** Initial Silicon

**Details:** If the Prescale Clock Divisor (PTV) value in the SPI setup register is 1 (SPI\_SET register bits [2:0] = 000) and the SPI is reading with a rising edge clock trigger, the DI serial read data will be incorrectly clocked into the SPI.

**Workaround:** Do not use a PTV value of 1. For a minimum, use a PTV value of 2 (SPI\_SET register bits [2:0] = 001). This gives a minimum cycle time for CLKX\_SPI of 168.4 ns with a minimum MCU cycle time of 21.05 ns;  $CLKX\_SPI = (MCU\ Clock / (4 * 2))$ .

No corrections are planned for future revisions.

**Advisory***SPI RE and WE Status Complete is Indicated Before the Last Bit is Processed*

**Revision(s) Affected:** Initial Silicon

**Details:** The SPI performs a transmission or reception of the last bit properly, but it incorrectly sets the SPI Status Register Write End (WE: SPI\_STATUS bit 1) or Read End (RE: SPI\_STATUS bit 0) bits before completion of the last bit. The status is not complete until the serial port clock (CLKX\_SPI) runs through its last period and external enable (MCUEN) deactivation.

Depending on the control settings of the SPI, it can take up to  $2^{1/2}$  CLKX\_SPI clock cycles to complete the SPI process after WE or RE are set to 1. Also, with a minimum setting of the prescale clock divisor (PTV), this could be as many as 640 MCU clocks ( $4 * 64 * 2^{1/2}$ ).

**Workaround:** None.

No corrections are planned for future revisions.

**Advisory***Reset During 16M/64M SDRAM Accesses Can Prevent the Device From Rebooting*

**Revision(s) Affected:** Initial Silicon

**Details:** When the SD\_SIZE bits in the SDRAM\_CONFIG register have been programmed for 16M or 64M sizes, the “Full Page Burst” option will be incorrectly selected. If a device reset occurs during an SDRAM access, the SDRAM (which does not have a hardware reset) continues to burst data. After the reset, the MCU will never receive its first instruction because the external boot memory (i.e., FLASH) shares the SDRAM bus.

Proper SDRAM initialization will occur when the SD\_SIZE is either 128M or 256M.

**Workaround:** Temporarily changing the SDRAM Size bits before and after the SDRAM initialization procedure will not affect the SDRAM size, since it is not a parameter of the SDRAM initialization procedure. The SDRAM initialization procedure should perform the following steps:

1. Load the SDRAM\_CONFIG register with the desired CAS Latency.
2. If SD\_SIZE bit 20 in the SDRAM\_CONFIG register is ‘0’ binary, then temporarily rewrite this bit to ‘1’ binary while the SDRAM initialization is in progress. Changing this bit will not affect the SDRAM Size, but will allow proper setting of the Burst Length.
3. Load the SDRAM\_INIT\_CONF register with an appropriate number of refresh cycles to be performed once the SDRAM is in the IDLE state. In addition, load this register with a clock cycle count larger than the delay required by the SDRAM. Typically, this delay is about 100  $\mu$ s. However, consult the SDRAM data sheet for the exact value required.
4. Start the SDRAM initialization procedure by activating the SDRAM\_INIT bit in SDRAM\_CNTL. There is no need to reset this bit, since it is self-clearing.
5. Wait for completion of the SDRAM initialization procedure by checking the READY bit in the SDRAM\_CNTL register. When READY is active, the SDRAM initialization is complete and the SDRAM is ready for normal operation.
6. If the SD\_SIZE bit 20 in the SDRAM\_CONFIG register was adjusted from ‘0’ binary to ‘1’ binary for the SDRAM initialization, then change it back to ‘0’ binary.

No corrections are planned for future revisions.

**Advisory***ARM/WAIT Does Not Operate Correctly*

**Revision(s) Affected:** Initial Silicon

**Details:** ARM/WAIT is improperly synchronized to ARM\_MCLK. Metastability issues can occur. Also, if ARM/WAIT is active at any time during a wait state counter cycle, another entire wait state cycle is restarted at the end of the present cycle versus the intended behavior of extending the bus access by a single ARM\_MCLK cycle at a minimum.

**Workaround:** None.

Do not use ARM/WAIT and tie the pin high with an external pullup. Increase the wait state setting for external memory spaces connected to slow external devices through the WS bits in the external memory control register (CS0\_REG–CS4\_REG: bits 4-0).

No corrections are planned for future revisions.

### 3 Documentation Support

For device-specific data sheets and related documentation, visit the TI web site at: <http://www.ti.com>

For further information regarding the TMS320VC5470, please refer to:

- *TMS320VC5470 Fixed-Point Digital Signal Processor* data manual, literature number SPRS017
- *TMS320VC547x CPU and Peripherals Reference Guide*, literature number SPRU038
- *TMS320C54x™ DSP Functional Overview*, literature number SPRU307

The five-volume *TMS320C54x DSP Reference Set*, literature number SPRU210, consisting of:

- *Volume 1: CPU and Peripherals*, literature number SPRU131
- *Volume 2: Mnemonic Instruction Set*, literature number SPRU172
- *Volume 3: Algebraic Instruction Set*, literature number SPRU179
- *Volume 4: Applications Guide*, literature number SPRU173
- *Volume 5: Enhanced Peripherals*, literature number SPRU302

The reference set describes in detail the TMS320C54x™ DSP products currently available and the hardware and software applications, including algorithms, for fixed-point TMS320™ DSP family of devices.

## IMPORTANT NOTICE

Texas Instruments Incorporated and its subsidiaries (TI) reserve the right to make corrections, modifications, enhancements, improvements, and other changes to its products and services at any time and to discontinue any product or service without notice. Customers should obtain the latest relevant information before placing orders and should verify that such information is current and complete. All products are sold subject to TI's terms and conditions of sale supplied at the time of order acknowledgment.

TI warrants performance of its hardware products to the specifications applicable at the time of sale in accordance with TI's standard warranty. Testing and other quality control techniques are used to the extent TI deems necessary to support this warranty. Except where mandated by government requirements, testing of all parameters of each product is not necessarily performed.

TI assumes no liability for applications assistance or customer product design. Customers are responsible for their products and applications using TI components. To minimize the risks associated with customer products and applications, customers should provide adequate design and operating safeguards.

TI does not warrant or represent that any license, either express or implied, is granted under any TI patent right, copyright, mask work right, or other TI intellectual property right relating to any combination, machine, or process in which TI products or services are used. Information published by TI regarding third-party products or services does not constitute a license from TI to use such products or services or a warranty or endorsement thereof. Use of such information may require a license from a third party under the patents or other intellectual property of the third party, or a license from TI under the patents or other intellectual property of TI.

Reproduction of information in TI data books or data sheets is permissible only if reproduction is without alteration and is accompanied by all associated warranties, conditions, limitations, and notices. Reproduction of this information with alteration is an unfair and deceptive business practice. TI is not responsible or liable for such altered documentation.

Resale of TI products or services with statements different from or beyond the parameters stated by TI for that product or service voids all express and any implied warranties for the associated TI product or service and is an unfair and deceptive business practice. TI is not responsible or liable for any such statements.

### Mailing Address:

Texas Instruments  
Post Office Box 655303  
Dallas, Texas 75265